YONKERS MIDDLE/HIGH SCHOOL

RECONSTRUCTION OF PORTIONS OF THE BLDG.

YPS NO.: 10812

EC CONTRACT 4: NABER

AE: CLARK PATTERSON LEE CM: SAVIN ENGINEERS, P.C. DATE PRINTED 11/22/2021

NYSED Part Two B: Requested By:	NYSED Part Two B: Relationship to Project Scope	NYSED Part Two C: Basis of Need	Category	NYSED Part Two D: Description	Status	Proposed Amount	Negotiated Amount	CO#
Owner	Additional scope of work within of project work area.	Existing PA system required 2 18/4 home runs from classrooms to head end. Contract documents called for 5 single runs.	Omission	Install 22 additional low voltage wiring for PA system, credit for 5 as per contract drawings.	Approved	\$17,766,24	\$13,135.00	9 11
	Additional scope of work within of project work area.	Contract documents called for ceiling tile replacement in corridor by library Electrical drawings did not show any work in area.	Omissions	Provide wire, labor to remove, safe off and reinstall 3rd Floor Ceiling Devices.	Approved	\$5,088.36	\$5,088.36	
Owner	Additional scope of work within of project work area.	Electrical feeders, panels and conduits needed to be relocated unforeseen prior to demolition.	Field Conditions	Relocate misc. conduits after demolition.	Approved	\$32,195.86	\$32,195.86	
Owner	Additional scope of work within of project work area	Found existing exhaust fans by loading dock were not connected to electrical source.	Field Conditions	Power to 2 existing exhaust fans by loading dock	Approved	\$1,660.53	\$1,660.53	
Owner	Additional scope of work within of project work area.	Found exhuast fan motor at loading dock not working after power was installed.	Field Conditions	Replace exhaust fan motor	Approved	\$2.015.69	\$1,300.86	
3/								
					COP Subtotal	\$58,726.68		ļ
	Two B: Requested By: Owner Owner Owner	Two B: Requested By: Additional scope of work within of project work area. Owner Additional scope of work within of project work area. Additional scope of work within of project work area. Owner Additional scope of work within of project work area. Owner Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area.	Two B: Requested By: Relationship to Project Scope Additional scope of work within of project work within of project work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Contract documents called for ceiling tile replacement in corridor by library Electrical drawings did not show any work in area. Additional scope of work within of project work area Additional scope of work within of project work area Additional scope of work within of project work area Additional scope of work within of project work area Additional scope of work within of project work area Found existing exhaust fans by loading dock were not connected to electrical source Found exhaust fan motor at loading dock not working after	Two B: Requested By: Relationship to Project Scope Additional scope of work within of project work area. Additional scope of work within of project work area Contract documents called for single runs. Contract documents called for ceiling tile replacement in corridor by library Electrical drawings did not show any work in area. Contract documents called for ceiling tile replacement in corridor by library Electrical drawings did not show any work in area. Contract documents called for ceiling tile replacement in corridor by library Electrical drawings did not show any work in area. Contract documents called for ceiling tile replacement in corridor by library Electrical drawings did not show any work in area. Field Conditions Contract documents called for ceiling tile replacement in corridor by library Electrical drawings did not show any work in area. Field Conditions Additional scope of work within of project work area Additional scope of work within of project work area Found existing exhaust fans by loading dock were not connected to electrical source Found exhuast fan motor at loading dock not working after	Two B: Requested By: Relationship to Project Scope Additional scope of work within of project work area. Contract documents called for ceiling tille replacement in corridor by library Electrical drawings did not show any work in area. Comer Owner Additional scope of work within of project work area Additional scope of work within of project work within of pr	Two B: Requested By: Relationship to Project Scope Relationship to Project Scope Additional scope of work within of project work area. Contract documents called for 5 single runs. Contract documents called for celling tile replacement in corridor by library Electrical drawings did not show any work in area. Contract documents called for celling tile replacement in corridor by library Electrical drawings did not show any work in area. Electrical feeders, panets and conduits needed to be relocated unforeseen prior to demolition. Comer Additional scope of work within of project work area Additional scope of work within of project work area Additional scope of work within of project work area Additional scope of work within of project work area Found existing exhaust fans by loading dock were not connected to electroal source work area Additional scope of work within of project work area Found existing exhaust fan motor at loading dock work not working after power was installed. Field Conditions Replace exhaust fan motor Approved Approved	Requested By: Relationship to Project Scope Owner Additional scope of work within of project work area. Commer Owner Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Additional scope of work within of project work area. Field Conditions Power to 2 existing exhaust fans by loading dock were not connected to electrical source work area. Approved \$1,660.53 Approved \$2,015.69	Requested By: Owner Project Scope Additional scope of work within of project work area. Contract documents called for Single runs. Owner Additional scope of work within of project work area. Contract documents called for Single runs. Owner Additional scope of work within of project work area. Contract documents called for Single runs. Owner Additional scope of work within of project work area. Contract documents called for Single runs. Owner Additional scope of work within of project work area. Contract documents called for Single runs. Owner Additional scope of work within of project work area. Contract documents called for Single runs. Owner Additional scope of work within of project work area. Contract documents called for Single runs. Owner Additional scope of work within of project work area. Contract documents called for Single runs. Owner Additional scope of work within of project work area. Contract documents called for Single runs. Contract documents called for Single runs. Omissions Omissions Provide wire, labor to remove, safe off and reinstall 3rd Floor Ceiling Devices. Approved \$55,088.36 \$5,

Total Proposed Fair & Reasonable \$53,380.61

Total Approved Change Orders \$53,380.61
Contract Allowance \$10,000.00

Balance of Allowance \$0 00 Original Contract Amount \$456,789 00

Revised Contract Amount \$500,169.61

Additional Amount of Change Orders / Additional Funds Required \$43,380.61 Total Amount of Change Orders \$43,380.61