



Playground Maintenance Corp.  
dba **PLAYGROUND MEDIC**

Playground Safety is Our Business!

146 Broadway

Hawthorne, New York, 10532

Phone# (866) 332-3133

Fax# (914) 747-3965

e-mail: [info@playgroundmedic.com](mailto:info@playgroundmedic.com)

**SERVICE AGREEMENT #22-585**

**Date:** August 8, 2022

**Customer:** Yonkers Public Schools

**Phone:** 914-376-8008

**Attn:** Meijo Kolancherry

**Fax:**

**One Larkin Center**

**E-mail:** [MKOLANCHERRY@YonkersPublicSchools.org](mailto:MKOLANCHERRY@YonkersPublicSchools.org)

**Yonkers, NY 10701**

**Scope of work: Playground Surfacing Replacement**

**Location: Paideia School #15, 175 Westchester Avenue, Yonkers, NY 10707**

**Job To Be Performed**

**Cost**

**Area #2 (Back of School) (Approx. 2,400 Square Feet)**

*Little Tikes Large Metal Composite Structure*

Remove & Dispose of existing rubber tiles

Remove & Dispose of protruding tree roots in playground area

Repair sub base as needed

Supply & Install approx. 200 Linear Feet of Nailer border in preparation for Turf

Supply & Install new Turf & padding

Estimated Labor for Removal

\$ 5,200.00

Estimated Cost for Disposal

\$ 4,920.00

Estimated Cost for Installation of Turf

\$ 39,675.00

Pad Thickness: 2 Inches

Critical Fall Height: 6 Feet

**APPROVED**  
Deputy Director of Facilities

**Note:**

1. Due to age & condition of existing equipment, Playground Medic **highly** recommends replacement of unit before installation of new Turf
2. Quotation is based upon sub base being in adequate condition. If severe damage to sub base is found upon removal of existing material, then additional costs may accrue

**Pricing generated per Yonkers Contract #2022-00000795**

**Purchase Order #2023-00000575**

**TOTAL**

**\$ 49,795.00**

**CUSTOMER SIGNATURE** \_\_\_\_\_ **DATE** \_\_\_\_\_

**PRINT NAME** \_\_\_\_\_ **TAX EXEMPT #** \_\_\_\_\_

**TITLE** \_\_\_\_\_ **CUSTOMER TOTAL** \_\_\_\_\_

**TERMS: NET 15 DAYS**