2/4/2025

Mr. Vincent Massaro City of Yonkers Office of General Services Yonkers, NY 10701

Description of Work: Asbestos Inspection -135 / 141 McLean Avenue, Yonkers, NY - Full Demolition

In response to your request for a cost estimate, LiRo has prepared the following scope and cost estimate for hazmat inspection and reporting services for the referenced Communications Room project.

| Labor Inspection Phase Hours | | x Rate/hr | | Multiplier | Cost | |
|--|---------------|------------------------|--------------------|------------|------|-----------|
| Project Manager | 4 | \$ | 60.00 | 2.49 | \$ | 597.60 |
| NYS DOL Asbestos Inspector | 32 | \$ | 42.50 | 2.49 | \$ | 3,386.40 |
| | | Total Inspection Labor | | | \$ | 3,984.00 |
| Labor - Reporting Phase | Hours | x Rate/hr | | Multiplier | | Cost |
| Project Manager | 16 | \$ | 60.00 | 2.49 | \$ | 2,390.40 |
| CADD Operator | 8 | \$ | 35.00 | 2.49 | \$ | 697.20 |
| | | | Total Design Labor | | \$ | 3,087.60 |
| Additional Services | | | Rate | Quantity | | Cost |
| Lab Testing | | | | | - | |
| Friable Material Testing - 198.1 Method | | \$ | 10.00 | 160 | \$ | 1,600.00 |
| Non-Friable Material Testing - 198.6 Method | | \$ | 17.00 | 125 | \$ | 2,125.00 |
| Non- Friable Material Testing - 198.5 Method | | \$ | 43.00 | 125 | \$ | 5,375.00 |
| | Estimated Lab | | | ted Lab | \$ | 9,100.00 |
| Reimbursables | | | | | | Cost |
| Contractor Assistance for Exploratory Probes / Roof Cuts / Test Pits | | | | | \$ | 7,000.00 |
| | | Total Reimbursables | | | \$ | 7,000.00 |
| | | Estimated Total | | | \$ | 23,171.60 |

Project Manager (Justin Tocci): The PM will coordinate daily field activities, review the sampling protocol, review the daily site logs and testing results, and prepare the final data report

Asbestos Inspector (TBD): The inspector will review the site plans, define/map bulk sampling locations, perform sampling, material inventory and quantification.

Lab Testing: Lab testing and equipment rentals have been estimated based on proposed scope of work

Note: 2 Structures with 3 construction dates: Storefront A, Storefront B, 3 Story House