

185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Insured: Cross Hill Contents

Estimator: Damian Reyes Business: (718) 652-0190 x 106

Company: Valcon Contracting Corp. E-mail: damian@valconcontractingco

rp.com

Claim Number: Type of Loss:

Date of Loss: 9/2/2021 11:49 PM Date Received:

Date Inspected: Date Entered: 11/8/2021 11:48 AM

Price List: NYWP8X_SEP21

Restoration/Service/Remodel

Estimate: CROSS_HILL-CONTENTS

This loss was cleaned a 2nd. time after suspended ceiling installed and the room was full of dust. School officials demanded the 2nd. cleaning

See page 30 for total "Contents Loss" of \$184,139.33.

The stated amount fully reimbursed by YPS insurance carrier Travelers.



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CROSS_HILL-CONTENTS

CROSS_HILL-CONTENTS

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
Bubble Wrap - Add-on cost for fragile items	500.00 LF	0.00	0.23	0.00	115.00	
2. Provide stretch film/wrap	1.00 RL	0.00	26.94	0.00	26.94	
3. Inventory, Packing, Boxing, and Moving charge - per hour	96.00 HR	0.00	55.76	0.00	5,352.96	
4 workers 8 hours each for 3 days to mo	ve packed contents fro	m the room that it was	packed to another room.			
4. Personal protective mask (N-95)	150.00 EA	0.00	4.10	0.00	615.00	
Total: CROSS_HILL-CONTENTS				0.00	6,109.90	
		Basement				
Basement						
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
5. Clean Electric Items (Bid Item)	1.00 EA	0.00	34,753.00	0.00	34,753.00	
Ers of Nothern NJ & Hudson Valley 17 Leslie Ct., Whippany NJ 07981 862-259-2413 Invoice # 01613						
Total: Basement				0.00	34,753.00	



Totals: Classroom 1

Valcon Contracting Corp.

185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Clas	sroom 1]	Height: 13' 5''
22'5"	1,952.58	1,952.58 SF Walls		1,421.90 SF Ceiling	
た	3,374.48	SF Walls & Ceiling	1,421.90 SF Floor		
5'4" 3' 4' 4" 8' 4' 1 5' 3" 3' 3' 3'		SY Flooring	14	8.22 LF Floor Peri	meter
3 3' 3' 3' 3' 3' 3' -3' -2 4' - 3 4''	157.55	LF Ceil. Perimeter			
25' 4"					
Window	3' X 3	•	Opens into Ex	terior	
Window	3' X 3	•	Opens into Ex	terior	
Window	3' X 3	•	Opens into Ex	terior	
Window	3' X 3	•	Opens into Ex	terior	
Window	3' X 3	•	Opens into Ex	terior	
Window	3' X 3	•	Opens into Ex	terior	
Window	3' X 3	,•	Opens into Ex	terior	
Window	3' X 3	,•	Opens into Exterior Opens into Exterior		
Window	3' X 3	,•			
Door	3' X 6	' 8''	Opens into Exterior		
Window	3' X 3	•	Opens into Ex	terior	
Window	3' X 3	•	Opens into Ex	terior	
Door	6' 4'']	X 6' 8"	Opens into HALLWAY		
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
*****CLEANING****					
6. Clean chair	6.00 EA	0.00	13.85	0.00	83.10
7. Clean furniture	14.00 EA	0.00	38.83	0.00	543.62
8. Clean desk	4.00 EA	0.00	26.25	0.00	105.00
9. Clean bookcase (per sf of face area)	100.00 SF	0.00	1.66	0.00	166.00
10. Clean bookcase contents	40.00 LF	0.00	9.68	0.00	387.20
11. Cleaning Technician - incl. cleaning agent - per hour	1.00 HR	0.00	47.11	0.00	47.11
To clean a divider 16LF and miscellaneous	us contents				
*****PACK-OUT****					
12. Evaluate, tag, & inventory miscellaneous - per item	1.00 EA	0.00	9.43	0.00	9.43

CROSS_HILL-CONTENTS 11/29/2021 Page: 3

0.00

1,341.46



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Classroom 2 & 2A

 1,672.86 SF Walls
 1,168

 2,841.51 SF Walls & Ceiling
 1,168

 129.85 SY Flooring
 129

138.47 LF Ceil. Perimeter

1,168.66 SF Ceiling 1,168.66 SF Floor 129.63 LF Floor Perimeter

Height: 13' 5"

F11'4"		
Door	3' X 6' 8"	Opens into CLASSROOM_2
Door	2' 10" X 6' 8"	Opens into HALLWAY
Door	3' X 6' 8''	Opens into HALLWAY
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
*****CLEANING****					
13. Clean chair	76.00 EA	0.00	13.85	0.00	1,052.60
14. Clean furniture - small	6.00 EA	0.00	28.05	0.00	168.30
15. Clean furniture	34.00 EA	0.00	38.83	0.00	1,320.22
16. Clean bookcase (per sf of face area)	40.00 SF	0.00	1.66	0.00	66.40
17. Clean bookcase contents	5.00 LF	0.00	9.68	0.00	48.40
18. Clean misc items - per Sml box - high density - Hvy Clean	6.00 EA	0.00	117.92	0.00	707.52
****PACK-OUT****					
19. Eval. pack & invent. misc items - per Sml box-high density	6.00 EA	0.00	21.62	0.00	129.72
20. Evaluate, tag, & inventory miscellaneous - per item	1.00 EA	0.00	9.43	0.00	9.43
Totals: Classroom 2 & 2A				0.00	3,502.59



Totals: Classroom 2B

Valcon Contracting Corp.

185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

<u> </u>	lassroom 2B		Height: 13' 5		
	1,294.57	SF Walls	588.43 SF Ceiling		
ClassroomC228srpo	1,883.00	SF Walls & Ceiling	58	38.43 SF Floor	
3 1 6′ 9″ 1	65.38	65.38 SY Flooring		98.17 LF Floor Peri	meter
6 9 1 3 3 3 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	104.17	LF Ceil. Perimeter			
6" 6" 5" •7' 1" • 3' 7"					
Door	3' X 6	5' 8''	Opens into CI	ASSROOM_4	
Door	3' X 6	5' 8''	Opens into CI	ASSROOM_2_	
Window	3' X 3	·	Opens into Ex	terior	
Window	3' X 3	·	Opens into Ex	terior	
Window	3' X 3	'	Opens into Ex	terior	
Window	3' X 3	, '	Opens into Ex	terior	
Window	3' X 3	, '	Opens into Exterior		
Window	3' X 3	,	Opens into Exterior		
Window	3' X 3	'	Opens into Exterior		
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
*****CLEANING****					
21. Clean chair	4.00 EA	0.00	13.85	0.00	55.40
22. Clean furniture - small	2.00 EA	0.00	28.05	0.00	56.10
23. Clean furniture	2.00 EA	0.00	38.83	0.00	77.66
24. Clean bookcase (per sf of face are	ea) 52.00 SF	0.00	1.66	0.00	86.32
25. Clean bookcase contents	7.00 LF	0.00	9.68	0.00	67.76
26. Clean file cabinet - two drawer - metal	2.00 EA	0.00	15.97	0.00	31.94
27. Clean misc items - per Sml box - high density - Hvy Clean	13.00 EA	0.00	117.92	0.00	1,532.96
****PACK-OUT****					
28. Eval. pack & invent. misc items - per Sml box-high density	13.00 EA	0.00	21.62	0.00	281.06
29. Evaluate, tag, & inventory miscellaneous - per item	1.00 EA	0.00	9.43	0.00	9.43

CROSS_HILL-CONTENTS 11/29/2021 Page: 5

0.00

2,198.63



Totals: Classroom 3A

Valcon Contracting Corp.

185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

_

5' 10" C	_5' 10" Classroom 3A			Height: 13' 5"		
1	907.51	907.51 SF Walls		243.61 SF Ceiling		
5 C 3/	1,151.13	SF Walls & Ceiling	2	43.61 SF Floor		
	27.07	SY Flooring		65.23 LF Floor Peri	meter	
25 1 2 6. 1 2 1 2 6.	82.07	82.07 LF Ceil. Perimeter				
3' 9"						
Door	3' X		-	LASSROOM_2		
Door		" X 6' 8"	Opens into H			
Door	3' X		-	ORAGE_AREA		
Window		'' X 4'	Opens into Ol			
Window		'' X 4'	Opens into Ol			
Door		X 6' 8"	Opens into Ol			
Door		X 6' 8"	-	Opens into OFFICE_3C		
Window		'' X 4'	Opens into OFFICE_3C			
Window	2' 10	2' 10" X 4'		Opens into OFFICE_3C		
Window	3' X	3' X 3'		Opens into Exterior		
Window	3' X	3'	Opens into Exterior			
Window	3' X	3'	Opens into Exterior			
Window	3' X	3'	Opens into Exterior			
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
*****CLEANING*****						
30. Clean chair	6.00 EA	0.00	13.85	0.00	83.10	
31. Clean furniture - small	6.00 EA	0.00	28.05	0.00	168.30	
32. Clean furniture	2.00 EA	0.00	38.83	0.00	77.66	
33. Clean misc items - per Sml box - high density - Hvy Clean	45.00 EA	0.00	117.92	0.00	5,306.40	
34. Clean misc items - per Med box - high density - Hvy Clean	1.00 EA	1.00 EA 0.00		143.59 0.00		
****PACK-OUT****						
35. Eval. pack & invent. misc items - per Sml box-high density	45.00 EA	0.00	21.62	0.00	972.90	
36. Eval. pack & invent. misc items - per Med box-high density	1.00 EA	0.00	26.31	0.00	26.31	
37. Evaluate, tag, & inventory miscellaneous - per item	1.00 EA	0.00	9.43	0.00	9.43	

CROSS_HILL-CONTENTS 11/29/2021 Page: 6

0.00

6,787.69



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Office 3B Height: 13' 2"


615.92 SF Walls 151.02 SF Ceiling 766.94 SF Walls & Ceiling 151.02 SF Floor

16.78 SY Flooring49.77 LF Ceil. Perimeter

47.27 LF Floor Perimeter

Window 2' 10" X 4' Opens into CLASSROOM_4
Window 2' 10" X 4' Opens into CLASSROOM_4
Door 2' 6" X 6' 8" Opens into CLASSROOM_4

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
38. Clean refrigerator - exterior	1.00 EA	0.00	21.63	0.00	21.63
39. Clean file cabinet - two drawer - metal	1.00 EA	0.00	15.97	0.00	15.97
40. Clean bookcase (per sf of face area)	18.00 SF	0.00	1.66	0.00	29.88
41. Clean bookcase contents	6.00 LF	0.00	9.68	0.00	58.08
Totals: Office 3B				0.00	125.56



	Height: 13' 4''

532.44 SF Walls
130.65 SF Ceiling
663.08 SF Walls & Ceiling
130.65 SF Floor
14.52 SY Flooring
44.43 LF Floor Perimeter
46.93 LF Ceil. Perimeter

Door	2' 6" X 6' 8"	Opens into CLASSROOM_
Window	2' 10" X 4'	Opens into CLASSROOM_
Window	2' 10" X 4"	Opens into CLASSROOM_
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior
Window	3' X 3'	Opens into Exterior

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
42. Clean file cabinet - four drawer - metal	1.00 EA	0.00	31.77	0.00	31.77
43. Clean furniture	1.00 EA	0.00	38.83	0.00	38.83



CROSS_HILL-CONTENTS

Valcon Contracting Corp.

185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CONTINUED - Office 3C

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
44. Clean bookcase (per sf of face area)	24.00 SF	0.00	1.66	0.00	39.84
45. Clean bookcase contents	8.00 LF	0.00	9.68	0.00	77.44
Totals: Office 3C				0.00	187.88

14:1 3:48:8" 4 4:1" ►13:7" → Class	sroom 4				Height: 13' 3"	
e \$43" (c) 1 4"	1,542.21	SF Walls	1,026.57 SF Ceiling			
3' 8" 10' 3" tock	2,568.78	SF Walls & Ceiling	1,026.57 SF Floor			
Cassioni 4		SY Flooring	11	18.15 LF Floor Per	rimeter	
21' 1" Sorag 21' 1" 3" 4"	132.90	LF Ceil. Perimeter				
Door	3' X 6	5' 8''	Opens into ST	ORAGE_4A		
Door	3' X 6	5' 8''	Opens into ST	OCK_4B		
Window	2' 8''	X 4'	Opens into OI	FFICE_4C2		
Window	2' 8''	X 4'	Opens into OI	FFICE_4C2		
Door	3' X 6	5' 8''	Opens into OI	FFICE_4C2		
Window	3' X 3	3'	Opens into Exterior			
Window	2' 11 15/16" X 4' 7/16"		Opens into Exterior			
Window	3' X 3'		Opens into Exterior			
Window	3' 1/8	3' 1/8" X 3' 11 1/2"		Opens into Exterior		
Window	3' X 3'		Opens into Exterior			
Window	3' X 3	3'	Opens into Exterior			
Window	3' X 3	3'	Opens into Exterior			
Window	3' X 3	3'	Opens into Exterior			
Window	2' 11	13/16" X 4' 3/16"	Opens into Exterior			
Window	3' X 3	3'	Opens into Exterior			
Door	5' 9''	X 6' 8"	Opens into HA	LLWAY		
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
*****CLEANING*****						
46. Clean chair	54.00 EA	0.00	13.85	0.00	747.90	
47. Clean stool	14.00 EA	0.00	13.88	0.00	194.32	
48. Clean furniture - small	6.00 EA	0.00	28.05	0.00	168.30	
49. Clean furniture	22.00 EA	0.00	38.83	0.00	854.26	
50. Clean television stand	1.00 EA	0.00	16.47	0.00	16.47	
51. Clean bookcase (per sf of face area)	144.00 SF	0.00	1.66	0.00	239.04	
-						

Page: 8


11/29/2021



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CONTINUED - Classroom 4

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
52. Clean bookcase contents	38.00 LF	0.00	9.68	0.00	367.84
53. Clean misc items - per Sml box - high density - Hvy Clean	223.00 EA	0.00	117.92	0.00	26,296.16
54. Clean misc items - per Med box - high density - Hvy Clean	19.00 EA	0.00	143.59	0.00	2,728.21
*****PACK-OUT****					
55. Eval. pack & invent. misc items - per Sml box-high density	223.00 EA	0.00	21.62	0.00	4,821.26
56. Eval. pack & invent. misc items - per Med box-high density	19.00 EA	0.00	26.31	0.00	499.89
57. Evaluate, tag, & inventory miscellaneous - per item	1.00 EA	0.00	9.43	0.00	9.43
58. Clean electric fan - portable	1.00 EA	0.00	34.98	0.00	34.98
Totals: Classroom 4				0.00	36,978.06



Storage 4A Height: 13' 3"

703.40 SF Walls880.98 SF Walls & Ceiling19.73 SY Flooring54.60 LF Ceil. Perimeter

177.58 SF Ceiling177.58 SF Floor51.60 LF Floor Perimeter

Door	3' X 6' 8''		Opens into CLASSROOM_5			
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
59. Clean bookcase (per sf of face area)	180.00 SF	0.00	1.66	0.00	298.80	
60. Clean bookcase contents	60.00 LF	0.00	9.68	0.00	580.80	
Totals: Storage 4A				0.00	879.60	



185 Summerfield Street

Scarsdale, NY 10583 Tel: 718-652-0190

7'6' 7'9"	Office 4C				Height: 13' 3''	
7-1-3-1-3-1-3-1-1-1 8-3-1-1-3-1-3-1-1-1-1-1-1-1-1-1-1-1-1-1-	446.44 SF Walls		10	102.90 SF Ceiling		
∑1 = 1 - 7' 6" - 7'	549.33	SF Walls & Ceiling	10	02.90 SF Floor		
7.Qffice 46/4"	11.43	SY Flooring	3	37.68 LF Floor Per	imeter	
So T T T T T T T T T T T T T T T T T T T	40.68	LF Ceil. Perimeter				
Window	2' 8'' 2	X 4'	Opens into CI	_ASSROOM_5		
Window	2' 8" 2	2' 8" X 4'		Opens into CLASSROOM_5		
Door	3' X 6	3' X 6' 8"		Opens into CLASSROOM_5		
Window	3' X 3	•	Opens into Exterior			
Window	3' X 4	' 3/8''	Opens into Exterior			
Window	3' 1/8'	' X 4' 1/8''	Opens into Exterior			
Window	3' X 3	•	Opens into Exterior			
Window	3' X 3	•	Opens into Exterior			
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
61. Clean coat rack	1.00 EA	0.00	20.48	0.00	20.48	
Totals: Office 4C				0.00	20.48	

3' 11" 4' 9" • 110' 3" • 1 3' 3' 3' 3'	Clasrrom 5]	Height: 15' 7"	
4" 7"-5Storage 5A	1,887.63	SF Walls	92	924.54 SF Ceiling		
3	2,812.17	SF Walls & Ceiling	92	24.54 SF Floor		
Clasrrom 5	102.73	SY Flooring	12	20.83 LF Floor Peri	meter	
17' 8" 1 3' 1" 15' 9" 1 5' 10" 5' 5' 15' 7" 1 Hallway	128.08	LF Ceil. Perimeter				
Hallway Door	4' 2" 2	X 6' 8''	Opens into ST	ORAGE_5A		
Window	3' X 3'	3' X 3'		Opens into Exterior		
Window	3' 1/8'	3' 1/8" X 3' 10 7/8"		Opens into Exterior		
Window	3' X 3'	•	Opens into Exterior			
Window	3' 3/16	5" X 4' 3/8"	Opens into Exterior			
Window	3' X 3'	•	Opens into Exterior			
Window	3' X 3'	•	Opens into Exterior			
Door	3' 1" 2	X 6' 8''	Opens into HALLWAY			
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
*****CLEANING****						
62. Clean chair	64.00 EA	0.00	13.85	0.00	886.40	


CROSS_HILL-CONTENTS Page: 10 11/29/2021



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CONTINUED - Clasrrom 5

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
63. Clean furniture - small	22.00 EA	0.00	28.05	0.00	617.10
64. Clean furniture	36.00 EA	0.00	38.83	0.00	1,397.88
65. Clean misc items - per Sml box - high density - Hvy Clean	150.00 EA	0.00	117.92	0.00	17,688.00
66. Clean misc items - per Med box - high density - Hvy Clean	14.00 EA	0.00	143.59	0.00	2,010.26
****PACK-OUT****					
67. Eval. pack & invent. misc items - per Sml box-high density	150.00 EA	0.00	21.62	0.00	3,243.00
68. Eval. pack & invent. misc items - per Med box-high density	14.00 EA	0.00	26.31	0.00	368.34
69. Evaluate, tag, & inventory miscellaneous - per item	1.00 EA	0.00	9.43	0.00	9.43
70. Clean file cabinet - four drawer - metal	3.00 EA	0.00	31.77	0.00	95.31
71. Clean bookcase (per sf of face area)	52.00 SF	0.00	1.66	0.00	86.32
72. Clean bookcase contents	16.00 LF	0.00	9.68	0.00	154.88
Totals: Clasrrom 5				0.00	26,556.92



Door

Door

Door

Classroom 7

1,583.48 SF Walls2,532.97 SF Walls & Ceiling105.50 SY Flooring125.64 LF Ceil. Perimeter

Height: 13' 5"

949.48 SF Ceiling949.48 SF Floor110.31 LF Floor Perimeter

3' X 6' 8"

Opens into OFFICE_7C

3' X 6' 8"

Opens into STORAGE_7B

3' X 6' 8"

Opens into STORAGE_7A

Opens into HALLWAY


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
*****CLEANING****					
73. Clean chair	56.00 EA	0.00	13.85	0.00	775.60
74. Clean furniture - small	36.00 EA	0.00	28.05	0.00	1,009.80
75. Clean furniture	6.00 EA	0.00	38.83	0.00	232.98
76. Clean misc items - per Sml box - high density - Hvy Clean	134.00 EA	0.00	117.92	0.00	15,801.28



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CONTINUED - Classroom 7

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
77. Clean misc items - per Med box - high density - Hvy Clean	3.00 EA	0.00	143.59	0.00	430.77
78. Clean bookcase contents	4.00 LF	0.00	9.68	0.00	38.72
79. Clean television stand	1.00 EA	0.00	16.47	0.00	16.47
****PACK-OUT****					
80. Eval. pack & invent. misc items - per Sml box-high density	134.00 EA	0.00	21.62	0.00	2,897.08
81. Eval. pack & invent. misc items - per Med box-high density	3.00 EA	0.00	26.31	0.00	78.93
82. Evaluate, tag, & inventory miscellaneous - per item	1.00 EA	0.00	9.43	0.00	9.43
Totals: Classroom 7				0.00	21,291.06



Storage 7B Height: 10'

401.68 SF Walls509.30 SF Walls & Ceiling11.96 SY Flooring42.17 LF Ceil. Perimeter


107.62 SF Ceiling107.62 SF Floor39.17 LF Floor Perimeter

Door	3' X 6' 8"		Opens into CLASSROOM_7			
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
83. Clean shelving - Metal	75.00 LF	0.00	1.95	0.00	146.25	
Totals: Storage 7B				0.00	146.25	
Total: Basement				0.00	134,769.18	

Main Level



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190



Room 114 Height: 10'

977.07 SF Walls 1,895.75 SF Walls & Ceiling 96.03 SY Flooring 124.62 LF Ceil. Perimeter 918.68 SF Ceiling 864.27 SF Floor 86.98 LF Floor Perimeter

Window	2' 10" X 7'	Opens into Exterior
Window	2' 10" X 7'	Opens into Exterior
Window	2' 10" X 7'	Opens into Exterior
Window	2' 10" X 7'	Opens into Exterior
Window	2' 10" X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Door	3' 1" X 6' 8"	Opens into HALLWAY


DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
84. Clean chair	38.00 EA	0.00	13.85	0.00	526.30
85. Clean stool	2.00 EA	0.00	13.88	0.00	27.76
86. Clean furniture - small	36.00 EA	0.00	28.05	0.00	1,009.80
87. Clean furniture	4.00 EA	0.00	38.83	0.00	155.32
88. Clean furniture - large	4.00 EA	0.00	60.39	0.00	241.56
89. Clean desk	2.00 EA	0.00	26.25	0.00	52.50
90. Clean desk contents	8.00 LF	0.00	9.56	0.00	76.48
91. Clean office chair	2.00 EA	0.00	45.13	0.00	90.26
92. Clean bookcase (per sf of face area)	43.00 SF	0.00	1.66	0.00	71.38
93. Clean bookcase contents	14.00 LF	0.00	9.68	0.00	135.52
94. Cleaning Technician - incl. cleaning agent - per hour	16.00 HR	0.00	47.11	0.00	753.76
2 workers 4 hours each to clean miscellane	eous contents in this	room twice			
95. Clean wastebasket/garbage/trash can	2.00 EA	0.00	6.24	0.00	12.48
96. Clean electric fan - portable	4.00 EA	0.00	34.98	0.00	139.92
97. Clean file cabinet - two drawer - metal	4.00 EA	0.00	15.97	0.00	63.88
98. Clean file cabinet - four drawer - metal	2.00 EA	0.00	31.77	0.00	63.54
99. Clean cabinet contents	48.17 LF	0.00	16.55	0.00	797.21
100. Clean window blind - roll up	3.00 EA	0.00	26.98	0.00	80.94



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CONTINUED - Room 114

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Totals: Room 114				0.00	4,298.61



Room 114A Height: 10'


956.85 SF Walls

1,535.60 SF Walls & Ceiling

64.31 SY Flooring

102.98 LF Ceil. Perimeter

Window 2' 10" X 7' Opens into Exterior
Window 2' 10" X 7' Opens into Exterior
Door 2' 6" X 6' 8" Opens into HALLWAY



Subroom: Room 114B (1) Height: 9'


284.02 SF Walls 55.80 SF Ceiling 339.82 SF Walls & Ceiling 55.80 SF Floor 6.20 SY Flooring 30.91 LF Floor Perimeter

2' 6" X 6' 8" Door Opens into ROOM_114A TOTAL DESCRIPTION OTY REMOVE REPLACE TAX 24.00 EA 0.00 13.85 0.00 101. Clean chair 332.40 6.00 EA 0.00 102. Clean furniture 0.00 38.83 232.98 103. Clean furniture - small 8.00 EA 0.00 0.0028.05 224.40 104. Clean desk 4.00 EA 0.00 26.25 0.00 105.00 105. Clean desk contents 6.00 LF 0.00 9.56 0.00 57.36 106. Clean office chair 4.00 EA 0.00 45.13 0.00 180.52 107. Cleaning Technician - incl. 16.00 HR 0.00 47.11 0.00 753.76 cleaning agent - per hour 2 workers 4 hours each to clean miscellaneous contents in this room twice. Large amount of contents Totals: Room 114A 0.001,886.42

33.41 LF Ceil. Perimeter



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190



Room 113 Height: 10'

1,014.56 SF Walls 2,067.55 SF Walls & Ceiling 114.98 SY Flooring 131.90 LF Ceil. Perimeter 1,052.99 SF Ceiling 1,034.84 SF Floor 100.86 LF Floor Perimeter

3' X 6' 8"	Opens into STORAGE_ARE2
3' 1" X 6' 8"	Opens into HALLWAY
3' X 7'	Opens into Exterior
3' X 7'	Opens into Exterior
3' X 7'	Opens into Exterior
3' X 7'	Opens into Exterior
3' X 7'	Opens into Exterior
3' X 7'	Opens into Exterior
3' X 7'	Opens into Exterior
3' X 7'	Opens into Exterior
3' X 7'	Opens into Exterior
	3' 1" X 6' 8" 3' X 7'

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
108. Clean chair	58.00 EA	0.00	13.85	0.00	803.30
109. Clean furniture - small	14.00 EA	0.00	28.05	0.00	392.70
110. Clean furniture	6.00 EA	0.00	38.83	0.00	232.98
111. Clean furniture - large	2.00 EA	0.00	60.39	0.00	120.78
112. Clean desk	2.00 EA	0.00	26.25	0.00	52.50
113. Clean desk contents	8.00 LF	0.00	9.56	0.00	76.48
114. Clean bookcase (per sf of face area)	80.00 SF	0.00	1.66	0.00	132.80
115. Clean bookcase contents	28.00 LF	0.00	9.68	0.00	271.04
116. Cleaning Technician - incl. cleaning agent - per hour	16.00 HR	0.00	47.11	0.00	753.76
2 workers 4 hours each to clean miscellan	eous contents in this	room twice			
117. Clean wastebasket/garbage/trash can	2.00 EA	0.00	6.24	0.00	12.48
118. Clean file cabinet - two drawer - metal	2.00 EA	0.00	15.97	0.00	31.94
119. Clean cabinet - metal	2.00 EA	0.00	31.77	0.00	63.54
120. Clean cabinet contents	48.33 LF	0.00	16.55	0.00	799.86
121. Clean electric fan - portable	2.00 EA	0.00	34.98	0.00	69.96
122. Clean file cabinet - four drawer - metal	2.00 EA	0.00	31.77	0.00	63.54



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CONTINUED - Room 113

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
Totals: Room 113				0.00	3,877.66

3:5+6:6"+ +3:43:43:4 Hock26(BL)	torage Area/Room				Height: 10'	
b' 3 + 6' 4" + 2"	414.65	SF Walls	22	223.17 SF Ceiling		
310-12-24-13-25 (\$22)	637.82	SF Walls & Ceiling	1:	57.32 SF Floor		
Slob 3 (B4)	17.48	SY Flooring	3	38.39 LF Floor Peri	meter	
Pas lage (#1); [H.5]	71.33	LF Ceil. Perimeter				
Door	3' X (3' X 6' 8"		Opens into ROOM_112		
Window	2' 6"	2' 6" X 3' 6"		Opens into ROOM_112		
Door	2' 6"	2' 6" X 6' 8"		Opens into PASSAGE		
Door	3' X (3' X 6' 8"		Opens into ROOM_113		
Window	3' X '	7'	Opens into Exterior			
Window	3' X '	7'	Opens into Ex	terior		
Window	3' X '	7'	Opens into Ex	terior		
DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL	
123. Clean cabinet contents	31.00 LF	0.00	16.55	0.00	513.05	
124. Clean cabinet contents - large an	mt 10.00 LF	0.00	19.70	0.00	197.00	
125. Clean bookcase contents	30.00 LF	0.00	9.68	0.00	290.40	
126. Cleaning Technician - incl. cleaning agent - per hour	16.00 HR	0.00	47.11	0.00	753.76	
127. Clean electric fan - portable	2.00 EA	0.00	34.98	0.00	69.96	

0.00

26.98

0.00

0.00

80.94

1,905.11

Height: 8'

1 assage (1) 5 1 2 10 1 5 1 5 5 5 1	Kitchen	Не
5.7.	175.67 SF Walls	68.08 SF Ceiling
Kitchen	243.75 SF Walls & Ceiling	38.48 SF Floor
	4.28 SY Flooring	9.80 LF Floor Perimeter
4 Block39 (BI)	33.33 LF Ceil. Perimeter	
4 Block 2 (B3)		

3.00 EA


128. Clean window blind - roll up

Totals: Storage Area/Room



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CONTINUED - Kitchen



Subroom: Passage (1) Height: 8'

> 78.24 SF Walls 12.61 SF Ceiling 90.85 SF Walls & Ceiling 12.61 SF Floor 1.40 SY Flooring

14.22 LF Ceil. Perimeter

2' 10" X 6' 8"

8.89 LF Floor Perimeter

TOTAL

720.20


0.00

Missing Wall - Goes to Floor

2' 6" X 6' 8" Door

Opens into KITCHEN Opens into STORAGE_ARE2

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
129. Clean cabinet contents - kitchen	37.33 LF	0.00	16.55	0.00	617.81
130. Clean countertop appliance	4.00 EA	0.00	14.37	0.00	57.48
131. Clean refrigerator - exterior	1.00 EA	0.00	21.63	0.00	21.63
Totals: Kitchen				0.00	696.92



132. Clean chair

Room 112 Height: 10'

> 1,007.25 SF Walls 1,054.66 SF Ceiling 2,061.91 SF Walls & Ceiling 1,009.44 SF Floor 112.16 SY Flooring 100.00 LF Floor Perimeter 132.00 LF Ceil. Perimeter

> > 13.85

· '9-12' 11" '9- 12' 1" '1				
Door	2' 6" X	<i>.</i> 6' 8''	Opens into HALL	WAY
Door	3' X 6'	8''	Opens into STOR	AGE_ARE2
Window	2' 6" X	3' 6"	Opens into STOR	AGE_ARE2
Window	2' 10" X 7' Opens into Ext			or
Window	3' X 7'		Opens into Exterio	or
Window	3' X 7'		Opens into Exterio	or
Window	3' X 7'		Opens into Exterio	or
Window	3' X 7'		Opens into Exterio	or
Window	3' X 7'		Opens into Exterio	or
Window	3' X 7'		Opens into Exterio	or
Window	3' X 7'		Opens into Exterio	or
Window	3' X 7'		Opens into Exterio	r
DESCRIPTION	QTY	REMOVE	REPLACE	TAX

52.00 EA

CROSS_HILL-CONTENTS 11/29/2021 Page: 17

0.00



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CONTINUED - Room 112

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
133. Clean stool	6.00 EA	0.00	13.88	0.00	83.28
134. Clean table - occasional	2.00 EA	0.00	15.22	0.00	30.44
135. Clean furniture - small	12.00 EA	0.00	28.05	0.00	336.60
136. Clean furniture	16.00 EA	0.00	38.83	0.00	621.28
137. Clean furniture - large	2.00 EA	0.00	60.39	0.00	120.78
138. Clean desk	2.00 EA	0.00	26.25	0.00	52.50
139. Clean desk contents	8.00 LF	0.00	9.56	0.00	76.48
140. Clean office chair	4.00 EA	0.00	45.13	0.00	180.52
141. Clean bookcase (per sf of face area)	76.00 SF	0.00	1.66	0.00	126.16
142. Clean bookcase contents	17.00 LF	0.00	9.68	0.00	164.56
143. Cleaning Technician - incl. cleaning agent - per hour	16.00 HR	0.00	47.11	0.00	753.76
2 workers 4 hours each to clean miscellar	neous contents in this	room twice			
144. Clean wastebasket/garbage/trash can	2.00 EA	0.00	6.24	0.00	12.48
145. Clean electric fan - portable	2.00 EA	0.00	34.98	0.00	69.96
146. Clean file cabinet - two drawer - metal	2.00 EA	0.00	15.97	0.00	31.94
147. Clean cabinet - metal	2.00 EA	0.00	31.77	0.00	63.54
148. Clean cabinet contents	49.33 LF	0.00	16.55	0.00	816.41
149. Clean window blind - roll up	6.00 EA	0.00	26.98	0.00	161.88
Totals: Room 112				0.00	4,422.77



Window Window Window Window Window Window Window

Door

Valcon Contracting Corp.

185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

20'8" 21'3' 8 Room 111 24'2" 3'8 Room 111 24'2" 3'8 Room 17'8" 17'

Room 111	Height: 10'

908.77 SF Ceiling

Opens into HALLWAY

854.06 SF Floor 87.00 LF Floor Perimeter
Opens into Exterior

947.38 SF Walls

3' 1" X 6' 8"

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
150. Clean chair	74.00 EA	0.00	13.85	0.00	1,024.90
151. Clean furniture - small	4.00 EA	0.00	28.05	0.00	112.20
152. Clean furniture	10.00 EA	0.00	38.83	0.00	388.30
153. Clean furniture - large	1.00 EA	0.00	60.39	0.00	60.39
154. Clean desk	2.00 EA	0.00	26.25	0.00	52.50
155. Clean desk contents	8.00 LF	0.00	9.56	0.00	76.48
156. Clean office chair	4.00 EA	0.00	45.13	0.00	180.52
157. Clean bookcase (per sf of face area)	25.50 SF	0.00	1.66	0.00	42.33
158. Clean bookcase contents	12.00 LF	0.00	9.68	0.00	116.16
159. Cleaning Technician - incl. cleaning agent - per hour	16.00 HR	0.00	47.11	0.00	753.76
2 workers 4 hours each to clean miscellar	neous contents in this	room twice			
160. Clean wastebasket/garbage/trash can	2.00 EA	0.00	6.24	0.00	12.48
161. Clean electric fan - portable	2.00 EA	0.00	34.98	0.00	69.96
162. Clean coat rack	2.00 EA	0.00	20.48	0.00	40.96
163. Clean cabinet contents	54.67 LF	0.00	16.55	0.00	904.79
Totals: Room 111				0.00	3,835.73



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Hallway

23 11 20 8"

17 4"

20 80 Room 110

20 80 30 110

224' 3"

211"

20' 10"

7' 4"

Room 110 Height: 10'

953.29 SF Walls	915.77 SF Ceiling
1,869.05 SF Walls & Ceiling	861.73 SF Floor
95.75 SY Flooring	87.84 LF Floor Perimeter
121.94 LF Ceil. Perimeter	

20' 10"		
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Door	3' 1" X 6' 8"	Opens into HALLWAY

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
164. Clean chair	70.00 EA	0.00	13.85	0.00	969.50
165. Clean furniture - small	8.00 EA	0.00	28.05	0.00	224.40
166. Clean furniture	22.00 EA	0.00	38.83	0.00	854.26
167. Clean furniture - large	1.00 EA	0.00	60.39	0.00	60.39
168. Clean desk	2.00 EA	0.00	26.25	0.00	52.50
169. Clean desk contents	8.00 LF	0.00	9.56	0.00	76.48
170. Clean bookcase (per sf of face area)	53.00 SF	0.00	1.66	0.00	87.98
171. Clean bookcase contents	24.00 LF	0.00	9.68	0.00	232.32
172. Cleaning Technician - incl. cleaning agent - per hour	16.00 HR	0.00	47.11	0.00	753.76
2 workers 4 hours each to clean miscellar	neous contents in this	room twice			
173. Clean wastebasket/garbage/trash can	2.00 EA	0.00	6.24	0.00	12.48
174. Clean electric fan - portable	4.00 EA	0.00	34.98	0.00	139.92
175. Clean cabinet contents	54.00 LF	0.00	16.55	0.00	893.70
176. Clean window blind - roll up	1.00 EA	0.00	26.98	0.00	26.98
Totals: Room 110				0.00	4,384.67



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Room 109 Height: 10' 951.34 SF Walls 910.90 SF Ceiling 1,862.24 SF Walls & Ceiling 856.90 SF Floor 95.21 SY Flooring 87.75 LF Floor Perimeter 121.67 LF Ceil. Perimeter Window 3' X 7' **Opens into Exterior** Door 3' X 6' 8" Opens into HALLWAY DESCRIPTION OTY REPLACE **TOTAL** REMOVE TAX 177. Clean chair 78.00 EA 0.00 13.85 0.00 1,080.30 0.00 178. Clean stool 2.00 EA 0.00 13.88 27.76 179. Clean furniture - small 18.00 EA 0.00 28.05 0.00 504.90 180. Clean furniture 22.00 EA 0.00 38.83 0.00 854.26 181. Clean desk 2.00 EA 0.00 26.25 0.00 52.50 182. Clean desk contents 8.00 LF 0.00 9.56 0.00 76.48 183. Clean office chair 2.00 EA 0.00 45.13 0.0090.26 184. Clean bookcase (per sf of face 43.00 SF 0.00 1.66 0.00 71.38 area) 185. Clean bookcase contents 14.00 LF 0.00 9.68 0.00 135.52 16.00 HR 0.00 47.11 0.00 753.76 186. Cleaning Technician - incl. cleaning agent - per hour 2 workers 4 hours each to clean miscellaneous contents in this room twice 2.00 EA 0.00 0.00 187. Clean wastebasket/garbage/trash 6.24 12.48 can 188. Clean electric fan - portable 4.00 EA 0.00 34.98 0.00 139.92 189. Clean file cabinet - two drawer -4.00 EA 0.00 15.97 0.00 63.88 metal 190. Clean cabinet - metal 2.00 EA 0.00 31.77 0.00 63.54 191. Clean cabinet contents 54.00 LF 0.00 16.55 0.00 893.70 Totals: Room 109 0.00 4,820.64



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

3 +" 7' 14' 14' 17' 2" 17' 2" 17' 2"
hissoin = 17 2 1 1 1 2 8 2 5 8 8 8 1 8 1 8 1 8 2 8 8 1 8 1 8 1 8 1 8
7' 1 7' 1 7' 1 7' 1 7' 1 7' 1 7' 1 7' 1
Bibot 40 (B1)Bib 124
24' 1" 3 11"

Room 108 Height: 10'

955.36 SF Walls	916.44 SF Ceiling
1,871.81 SF Walls & Ceiling	862.61 SF Floor
95.85 SY Flooring	88.48 LF Floor Perimeter
122.00 LF Ceil. Perimeter	

20' 8" - 7' 5"		
Door	3' 1" X 6' 8"	Opens into HALLWAY
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
192. Clean chair	38.00 EA	0.00	13.85	0.00	526.30
193. Clean projector screen	96.00 SF	0.00	0.73	0.00	70.08
194. Clean furniture - large	2.00 EA	0.00	60.39	0.00	120.78
195. Clean furniture - small	18.00 EA	0.00	28.05	0.00	504.90
196. Clean furniture	20.00 EA	0.00	38.83	0.00	776.60
197. Clean desk	4.00 EA	0.00	26.25	0.00	105.00
198. Clean desk contents	8.50 LF	0.00	9.56	0.00	81.26
199. Clean office chair	4.00 EA	0.00	45.13	0.00	180.52
200. Clean bookcase (per sf of face area)	20.00 SF	0.00	1.66	0.00	33.20
201. Clean bookcase contents	8.00 LF	0.00	9.68	0.00	77.44
202. Cleaning Technician - incl. cleaning agent - per hour	8.00 HR	0.00	47.11	0.00	376.88
2 workers 2 hours each to clean miscella	neous contents in this	room twice			
203. Clean cabinet contents	53.83 LF	0.00	16.55	0.00	890.89
Totals: Room 108	-			0.00	3,743.85



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

T 4 /T	TT 1 1 4 401
Entry/Foyer	Height: 10'

982.18 SF Walls	942.75 SF Ceiling
1,924.93 SF Walls & Ceiling	942.75 SF Floor
104.75 SY Flooring	97.72 LF Floor Perimeter
120.14 LF Ceil. Perimeter	

Window	1' 6" X 4'	Opens into STAIRS1
Door	3' X 6' 8"	Opens into STAIRS1
Window	1' 6" X 4'	Opens into STAIRS1
Door	3' X 6' 8"	Opens into STAIRS1
Window	1' 6'' X 4'	Opens into STAIRS1
Missing Wall	10' 6 5/16" X 10'	Opens into Exterior
Window	2' X 6'	Opens into Exterior
Window	2' X 6'	Opens into Exterior
Door	5' 8'' X 7'	Opens into Exterior
Door	5' 8'' X 7'	Opens into Exterior
Window	2' X 6'	Opens into Exterior
Window	2' X 6'	Opens into Exterior
Door	5' 1" X 6' 8"	Opens into ROOM13

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
204. Clean desk	2.00 EA	0.00	26.25	0.00	52.50
205. Clean desk contents	2.00 LF	0.00	9.56	0.00	19.12
206. Clean furniture - large	2.00 EA	0.00	60.39	0.00	120.78
207. Clean office chair	4.00 EA	0.00	45.13	0.00	180.52
208. Clean chair	4.00 EA	0.00	13.85	0.00	55.40
209. Clean cart	2.00 EA	0.00	20.17	0.00	40.34
210. Clean stereo - components - speakers - exterior wipe down	2.00 EA	0.00	12.13	0.00	24.26
	·	·			

Totals: Entry/Foyer 0.00 492.92




Window

Valcon Contracting Corp.

185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

> **Asst. Principal** Height: 14' 2"



1,286.78 SF Walls 1,690.42 SF Walls & Ceiling 44.85 SY Flooring

403.64 SF Ceiling 403.64 SF Floor

3' X 7'

99.11 LF Ceil. Perimeter

94.11 LF Floor Perimeter

Window	
Window	
Window	
Door	

Opens into Exterior 3' X 7' **Opens into Exterior** 3' X 7' **Opens into Exterior** 3' X 7' **Opens into Exterior** 2' 6" X 6' 8" **Opens into Exterior**



Subroom: Restroom (1)

Height: 14' 2"

209.47 SF Walls

223.30 SF Walls & Ceiling

1.54 SY Flooring

15.96 LF Ceil. Perimeter

13.83 SF Ceiling

13.83 SF Floor

13.46 LF Floor Perimeter

Door

2' 6" X 6' 8"

Opens into ASST_PRINCI

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
211. Clean chair	16.00 EA	0.00	13.85	0.00	221.60
212. Clean furniture - small	4.00 EA	0.00	28.05	0.00	112.20
213. Clean furniture - large	4.00 EA	0.00	60.39	0.00	241.56
214. Clean file cabinet - four drawer - metal	2.00 EA	0.00	31.77	0.00	63.54
215. Clean desk	2.00 EA	0.00	26.25	0.00	52.50
216. Clean desk contents	8.00 LF	0.00	9.56	0.00	76.48
217. Clean wastebasket/garbage/trash can	2.00 EA	0.00	6.24	0.00	12.48
218. Clean refrigerator - exterior	1.00 EA	0.00	21.63	0.00	21.63
219. Cleaning Technician - incl. cleaning agent - per hour	4.00 HR	0.00	47.11	0.00	188.44
to clean miscellaneous contents					
220. Clean cabinet - metal	2.00 EA	0.00	31.77	0.00	63.54
221. Clean window blind - roll up	4.00 EA	0.00	26.98	0.00	107.92
Totals: Asst. Principal				0.00	1,161.89

CROSS_HILL-CONTENTS Page: 24 11/29/2021




185 Summerfield Street Scarsdale, NY 10583

Tel: 718-652-0190

Total: Main Level 0.00 35,527.19

Level 2

	Hallway	Height: 10
	2,105.55 SF Walls	1,623.95 SF Ceiling
BECK 110 51 9 :	3,729.50 SF Walls & Ceiling	1,407.94 SF Floor
Annual Control of the	156.44 SY Flooring	252.49 LF Floor Perimeter
	288.74 LF Ceil. Perimeter	
Door	3' X 6' 8"	Opens into Exterior
Door	3' X 6' 8"	Opens into ROOM_214
Door	3' X 6' 8"	Opens into Exterior
Door	3' X 6' 8"	Opens into Exterior
Window	1' 6" X 4'	Opens into STAIRS5
Door	3' 6" X 6' 8"	Opens into STAIRS5
Window	1' 6'' X 4'	Opens into STAIRS5
Door	3' 6" X 6' 8"	Opens into STAIRS5
Window	1' 6" X 4'	Opens into STAIRS5
Door	3' X 6' 8"	Opens into Exterior
Door	3' X 6' 8"	Opens into Exterior
Door	3' X 6' 8"	Opens into Exterior
Door	3' X 6' 8"	Opens into Exterior



Subroom: Closet (2) Height: 10'

> 349.94 SF Walls 81.04 SF Ceiling 430.98 SF Walls & Ceiling 81.04 SF Floor 34.16 LF Floor Perimeter 9.00 SY Flooring 36.66 LF Ceil. Perimeter

Opens into ROOM13 2' 6" X 6' 8" Door



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

CONTINUED - Hallway



Subroom: Room13 (1) Height: 10'

 1,045.07 SF Walls
 740.13 SF Ceiling

 1,785.19 SF Walls & Ceiling
 740.13 SF Floor

 82.24 SY Flooring
 96.84 LF Floor Perimeter

119.84 LF Ceil. Perimeter


5' 3" X 6' 8" Opens into HALLWAY Door 2' 6" X 6' 8" **Opens into Exterior** Door Door 2' 6" X 6' 8" **Opens into Exterior Missing Wall** 10' 9 5/16" X 10' **Opens into Exterior** 2' 6" X 6' 8" Opens into ASST_PRINCI Door 2' 6" X 6' 8" Door **Opens into CLOSET** Door 5' 3" X 6' 8" **Opens into Exterior**

Door 5' 3" X 6' 8" Opens into Exterior
Door 2' 6" X 6' 8" Opens into Exterior

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
222. Clean furniture - large	2.00 EA	0.00	60.39	0.00	120.78
223. Clean chair	4.00 EA	0.00	13.85	0.00	55.40
224. Clean office chair	2.00 EA	0.00	45.13	0.00	90.26
Totals: Hallway				0.00	266.44



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190



Room 213 Height: 10'


1,043.78 SF Walls	1,097.33 SF Ceiling
2,141.12 SF Walls & Ceiling	1,024.23 SF Floor
113.80 SY Flooring	91.31 LF Floor Perimeter
135.67 LF Ceil. Perimeter	

25.3.		
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	3' X 7'	Opens into Exterior
Window	2' 10" X 7'	Opens into Exterior
Window	2' 10" X 7'	Opens into Exterior
Door	3' X 6' 8"	Opens into HALLWAY
Door	3' X 6' 8''	Opens into Exterior

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
225. Clean chair	58.00 EA	0.00	13.85	0.00	803.30
226. Clean furniture	6.00 EA	0.00	38.83	0.00	232.98
227. Clean desk	60.00 EA	0.00	26.25	0.00	1,575.00
228. Clean desk contents	8.00 LF	0.00	9.56	0.00	76.48
229. Clean furniture - large	8.00 EA	0.00	60.39	0.00	483.12
230. Clean office chair	2.00 EA	0.00	45.13	0.00	90.26
231. Clean bookcase (per sf of face area)	36.00 SF	0.00	1.66	0.00	59.76
232. Clean bookcase contents	6.00 LF	0.00	9.68	0.00	58.08
233. Cleaning Technician - incl. cleaning agent - per hour	8.00 HR	0.00	47.11	0.00	376.88
2 workers 4 hours each to clean miscellan	neous contents in this	room twice			
234. Clean wastebasket/garbage/trash can	2.00 EA	0.00	6.24	0.00	12.48
235. Clean file cabinet - four drawer - metal	2.00 EA	0.00	31.77	0.00	63.54
236. Clean cabinet contents	64.67 LF	0.00	16.55	0.00	1,070.29
237. Clean window blind - roll up	9.00 EA	0.00	26.98	0.00	242.82
Totals: Room 213				0.00	5,144.99



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190



Asst. Principal

Height: 10'

949.06 SF Walls 1,555.38 SF Walls & Ceiling 65.91 SY Flooring 105.33 LF Ceil. Perimeter 606.32 SF Ceiling 593.15 SF Floor 90.70 LF Floor Perimeter


Door 2' 6" X 6' 8"
Window 3' X 7'
Window 3' X 7'
Door 2' 6" X 6' 8"

Opens into ROOM_200A_ST Opens into Exterior Opens into Exterior Opens into ROOM13

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
238. Clean chair	10.00 EA	0.00	13.85	0.00	138.50
239. Clean furniture	2.00 EA	0.00	38.83	0.00	77.66
240. Clean furniture - large	6.00 EA	0.00	60.39	0.00	362.34
241. Clean file cabinet - four drawer - metal	2.00 EA	0.00	31.77	0.00	63.54
242. Clean desk	2.00 EA	0.00	26.25	0.00	52.50
243. Clean desk contents	8.00 LF	0.00	9.56	0.00	76.48
244. Clean office chair	4.00 EA	0.00	45.13	0.00	180.52
245. Clean wastebasket/garbage/trash can	2.00 EA	0.00	6.24	0.00	12.48
246. Clean refrigerator - exterior	1.00 EA	0.00	21.63	0.00	21.63
247. Cleaning Technician - incl. cleaning agent - per hour	4.00 HR	0.00	47.11	0.00	188.44
to clean miscellaneous contents					
248. Clean file cabinet - two drawer - metal	2.00 EA	0.00	15.97	0.00	31.94
249. Clean window blind - roll up	4.00 EA	0.00	26.98	0.00	107.92
250. Clean bookcase (per sf of face area)	36.00 SF	0.00	1.66	0.00	59.76
251. Clean bookcase contents	12.00 LF	0.00	9.68	0.00	116.16
252. Clean table - occasional	4.00 EA	0.00	15.22	0.00	60.88
253. Clean sofa	4.00 EA	0.00	47.65	0.00	190.60
Totals: Asst. Principal				0.00	1,741.35



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190



Room 200A Storage

445.89 SF Walls 579.69 SF Walls & Ceiling 14.87 SY Flooring

46.26 LF Ceil. Perimeter

Height: 10'

133.80 SF Ceiling 133.80 SF Floor

43.76 LF Floor Perimeter

Door 2' 6" X 6' 8" Opens into ASST_PRINCI

DESCRIPTION	QTY	REMOVE	REPLACE	TAX	TOTAL
254. Clean file cabinet - four drawer - metal	6.00 EA	0.00	31.77	0.00	190.62
255. Clean furniture - large	2.00 EA	0.00	60.39	0.00	120.78
256. Clean bookcase (per sf of face area)	92.00 SF	0.00	1.66	0.00	152.72
257. Clean bookcase contents	12.00 LF	0.00	9.68	0.00	116.16
Totals: Room 200A Storage				0.00	580.28
Total: Level 2				0.00	7,733.06
Line Item Totals: CROSS_HILL-CON	ITENTS			0.00	184,139.33

Grand Total Areas:

53,828.76	SF Walls	28,441.16	SF Ceiling	82,269.91	SF Walls and Ceiling
28,327.25	SF Floor	3,147.47	SY Flooring	4,530.06	LF Floor Perimeter
0.00	SF Long Wall	0.00	SF Short Wall	5,172.69	LF Ceil. Perimeter
28,327.25	Floor Area	29,865.29	Total Area	44,230.15	Interior Wall Area
20,643.68	Exterior Wall Area	1,978.57	Exterior Perimeter of Walls		
0.00	Surface Area	0.00	Number of Squares	0.00	Total Perimeter Length
0.00	Total Ridge Length	0.00	Total Hip Length		

Coverage	Item Total	%	ACV Total	%
Dwelling	0.00	0.00%	0.00	0.00%
Other Structures	0.00	0.00%	0.00	0.00%
Contents	184,139.33	100.00%	184,139.33	100.00%
Total	184,139.33	100.00%	184,139.33	100.00%



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Summary for Contents

Line Item Total		184,139.33
Replacement Cost Value		\$184,139.33
Net Claim		\$184,139.33
	Damian Reyes	



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Recap of Taxes



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Recap by Room

Estimate: CROSS_HILL-CONTENTS		6,109.90	3.32%
Coverage: Contents	100.00% =	6,109.90	
Area: Basement		34,753.00	18.87%
Coverage: Contents	100.00% =	34,753.00	
Classroom 1		1,341.46	0.73%
Coverage: Contents	100.00% =	1,341.46	
Classroom 2 & 2A		3,502.59	1.90%
Coverage: Contents	100.00% =	3,502.59	
Classroom 2B		2,198.63	1.19%
Coverage: Contents	100.00% =	2,198.63	
Classroom 3A		6,787.69	3.69%
Coverage: Contents	100.00% =	6,787.69	
Office 3B		125.56	0.07%
Coverage: Contents	100.00% =	125.56	
Office 3C		187.88	0.10%
Coverage: Contents	100.00% =	187.88	
Classroom 4		36,978.06	20.08%
Coverage: Contents	100.00% =	36,978.06	
Storage 4A		879.60	0.48%
Coverage: Contents	100.00% =	879.60	
Office 4C		20.48	0.01%
Coverage: Contents	100.00% =	20.48	
Clasrrom 5		26,556.92	14.42%
Coverage: Contents	100.00% =	26,556.92	
Classroom 7		21,291.06	11.56%
Coverage: Contents	100.00% =	21,291.06	
Storage 7B		146.25	0.08%
Coverage: Contents	100.00% =	146.25	
Area Subtotal: Basement	_	134,769.18	73.19%
Coverage: Contents	100.00% =	134,769.18	
Area: Main Level			
Room 114		4,298.61	2.33%
Coverage: Contents	100.00% =	4,298.61	
Room 114A		1,886.42	1.02%
Coverage: Contents	100.00% =	1,886.42	
Room 113		3,877.66	2.11%
Coverage: Contents	100.00% =	3,877.66	
Storage Area/Room		1,905.11	1.03%
Coverage: Contents	100.00% =	1,905.11	
Kitchen		696.92	0.38%
CROSS_HILL-CONTENTS		11/29/2021	Page: 32



185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190


	Coverage: Contents	100.00% =	696.92	
-	Room 112	100.00% =	4,422.77	2.40%
	Coverage: Contents	100.00% =	4,422.77	_,,,,
	Room 111		3,835.73	2.08%
	Coverage: Contents	100.00% =	3,835.73	
	Room 110		4,384.67	2.38%
	Coverage: Contents	100.00% =	4,384.67	
-	Room 109		4,820.64	2.62%
	Coverage: Contents	100.00% =	4,820.64	
	Room 108		3,743.85	2.03%
	Coverage: Contents	100.00% =	3,743.85	
]	Entry/Foyer		492.92	0.27%
	Coverage: Contents	100.00% =	492.92	
	Asst. Principal		1,161.89	0.63%
	Coverage: Contents	100.00% =	1,161.89	
	Area Subtotal: Main Level		35,527.19	19.29%
	Coverage: Contents	100.00% =	35,527.19	
Area: L	evel 2			
	Hallway		266.44	0.14%
	Coverage: Contents	100.00% =	266.44	
-	Room 213		5,144.99	2.79%
	Coverage: Contents	100.00% =	5,144.99	
	Asst. Principal		1,741.35	0.95%
	Coverage: Contents	100.00% =	1,741.35	
	Room 200A Storage		580.28	0.32%
	Coverage: Contents	100.00% =	580.28	
	Area Subtotal: Level 2		7,733.06	4.20%
	Coverage: Contents	100.00% =	7,733.06	
Subtota	l of Areas		184,139.33	100.00%
	Coverage: Contents	100.00% =	184,139.33	
Total			184,139.33	100.00%




185 Summerfield Street Scarsdale, NY 10583 Tel: 718-652-0190

Recap by Category


Items			Total	%
CONT: CLEAN APPLIANCES			792.06	0.43%
Coverage: Contents	@	100.00% =	792.06	
CONT: CLEAN ELECTRIC ITEMS			34,777.26	18.89%
Coverage: Contents	@	100.00% =	34,777.26	
CONT: CLEAN - GENERAL ITEMS			92,700.55	50.34%
Coverage: Contents	@	100.00% =	92,700.55	
CONT: CLEAN - HARD FURNITUR	E		33,818.65	18.37%
Coverage: Contents	@	100.00% =	33,818.65	
CLEANING			1,112.25	0.60%
Coverage: Contents	@	100.00% =	1,112.25	
CONT: PACKING, HANDLNG, STOR	RAGE		18,879.40	10.25%
Coverage: Contents	@	100.00% =	18,879.40	
CONT: CLEAN, UPHOLSTERY & S	OFT		1,444.16	0.78%
Coverage: Contents	@	100.00% =	1,444.16	
WATER EXTRACTION & REMEDI	ATION		615.00	0.33%
Coverage: Contents	@	100.00% =	615.00	
Subtotal			184,139.33	100.00%



Basement









Level 2